

Industrial Gauge and Duratemp® Pointer Options

Pointer Options

XSH - Stationary Red Set Hand (On Dial)

XEO - External Adjustable Red Set Hand with Knob (On Window)



1009
2½" dial with back flange



C-600A-03



1009
4½" dial

Model/Dial Size

1008	Sizes 63 and 100mm
1009	Sizes 2½", 3½", 4½" and 6"
2008	Size 63mm
C-600A/600B/600H	Sizes 4½", 6", 8½"

Note: XSJ Dual Stationary Pointers is valid for 1008, 1009 and 2008 listed above

Model/Dial Size

1009	Sizes 4½" and 6"
C-600A/600B/600H	Sizes 4½" and 6"
N/A with liquid fill units	

XEO - External Adjustable Red Set Hand (On Window)

XEP - External Adjustable Pointer (Min./Max.)



1009
2½" dial



1009
4½" dial



C-600A-01

Model/Dial Size

1009	Sizes 2½" and 3½"
------	-------------------

Note: N/A with liquid fill units

Model/Dial Size

1009	Sizes 4½" and 6"
C-600A/600B/600H	Sizes 4½" and 6"
N/A with liquid fill units	

Industrial Gauge and Duratemp[®] Pointer Options

Pointer Options

XED, XEE, XEF, XEG - Electric Contacts



C-600A-02

Model/Dial Size

C-600A-02	Sizes 4½" and 6"
C-600A-03	
C-600A-04	

Options

ED	High and Low
EE	Double High
EF	Double Low
EG	Low and High